



NARRATIVE INSPECTION REPORT DOCUMENT

Date	of In	spection	n:		3/2	28/9	90				 Inspecto	or:	JAMES	HAE	NNICKE	-
Site	Code:	0 3	1	6	0	0	0	0	3	4	County:		соок			
Site	Name:	LANI	3 C	LAI	KES	#3	•						T	ime:	7:20-8:30	a.m.

GENERAL REMARKS

Land & Lakes 3 is currently waiting on new activated carbon for their temporary liquid waste treatment equipment. Their waste water pond is at about the same level as my last inspection. Mark hopes to start treating the liquid soon as they have had to push clay up against the adjoining excavation pit wall in order to stop the egress of leachate.

APPARENT VIOLATIONS

- LINE 5 Due to dry on-site roads, dust caused a notable problem as seen in photos 1 & 3. Mark stated that their water truck was inoperable and currently in the on-site maintenance shop.
- LINE 26 Photo 6 depicts a small stream of leachate emanating from the road in the filled western portion of Land & Lakes. Mark asked if covering the area with clay, as in past practices, would be sufficient. I reminded him that this would only be a temporary solution. My suggestion was to include a leachate collecting concrete culvert in addition to the clay. When asked if the leachate pumped from the culvert could be deposited with the daily refuse in the active area I told Mark to transfer it instead to their wastewater pond. Here it could be permanently treated so as not to pose any problems in the future.

LINE 27 Water truck inoperable.

Land & Lakes Daily Waste Record for 3/27/90 shows 445 cubic yards of special waste and 434 cubic yards of regular waste subject to the State fee. Ticket collector Henry Franc said that the low totals are probably due to the presence of state officials checking the scale.

RECEIVED
- 5 APR 1990
IEPA/DLPC

NARRATIVE INSPECTION REPORT DOCUMENT (continued)

Page 2 of 2

Site Code: 0316000034

Inspection Date: 3/28/90

FOLLOW-UP INVESTIGATION

Land & Lake's superintendent Bob Kras called me shortly after the inspection stating that clay was applied to the area where leachate was present and that a concrete culvert was being installed. He asked if I would come out and verify that compliance was being initiated.

I met with Bob and Mark at 9:00 a.m. on 3/30/90, for a follow-up inspection. The leachate problem was remedied by the above mentioned actions. Also, in regard to their dust violation, Land & Lakes 3 has on site a spare water truck from their maintenance garage on 134th street.

During this visit, Land & Lakes 3 was found to be in compliance.

STATE OF ILLINOIS ENVIRONMENTAL PROTECTION AGENCY

SITE SKETCH

Date of Inspection: 3/28/90	Inspector: JAMES HAENNICKE
Site Code: 0 3 1 6 0 0 0 0 3 4	County: COOK
Site Name: LANE & LAKES #3	Time: 7:20-8:30 a.m.
A- ACTIVE AREA	B- CURRENT ACTIVE AREA
SAUDGE OF STOCK PILES DAN TREATMENT PLANT	POOLED RAIN WATER B EXCAVATION PIT RECEIVED - 5 APR 1990 WATER / LEACHATE PIT WATER / LEACHATE PIT

3/28/90

ле: 7:20-8:30 a.m.

otograph By:

JAMES HAENNICKE

ty:_ CHICAGO

PA # 5 07160000°4

te Name:

LAND & LAKES #3

nments:__EAST

ACTIVE AREA; DUST

to # 1 Roll #, 90-293

:e: 3/28/90

ne: 7:20-8:30 a.m.

stograph By:

JAMES HAENNICKE

y: CHICAGO

A # . 0316000034

e Name:


LAND & LAKES #3

ments:__SOUTH

INCLEMENT WEATHER

ACTIVE AREA

to = 2 Roll = 90-293



RECEIVED - 5 APR 1990

IEPA/DLPC



3/28/90			/
me: 7:20-8:30 a.m.	THE ALL THE PERSON OF THE PERS		
Photograph By: JAMES HAENNICKE			
city: CHICAGO			
EPA #: 0316000034		Total Statement (1) to a control of the control of	1
ite Name:			The second second
LAND & LAKES #3			
omments: NORTH			
EXCAVATION PIT; DUST	A Committee of the Comm		
		The state of the s	
3/28/90 ime: 7:20-8:30 a.m.			
hotograph By: JAMES HAENNICKE			
ity: CHICAGO	THE STATE OF THE S		
EPA #		a dia	100
ite Name: LAND & LAKES #3			
	777	No.	7-3-1
omments: SOUTHWEST	* P. P.		
EXCAVATION PIT			
	-		-
The state of the s	1 200		
noto = 4 Roll = 90-293			

*

3/28/90

/me: 7:20-8:30 a.m.

hotograph By:

JAMES HAENNICKE

City: CHICAGO

EPA # 3 0316000034

ite Name:

LAND & LAKES #3

omments: NORTH

POOLED RAIN WATER

hoto # 5 Roll #, 90-293

ate: 3/28/90

ime: 7:20-8:30 a.m.

notograph By:

JAMES HAENNICKE

ity: CHICAGO

PA # 0316000034

te Name:

LAND & LAKES #3

mments:__NORTH

LEACHATE STREAM

oto = 6 Roll = 90-293



